


6. Accidental release measures



	Personal precautions:	Not applicable	\wedge
	Environmental precautions:	See section 12 & 13	
	Methods for cleaning up:	See section 13	
			A I.C.
7. Handling and storage			
Handling:	Technical measures: Precautions: Safe handling advice:	Not applicable Not applicable During machining of the stock shapes, evacuate swarf to p or tripping hazard	event stipping
Storage:	Technical measures: Safe storage conditions: Incompatible products: Safe packaging materials:	Avoid exposure to UV-radiation Inert under normal storage conditions Not applicable Not applicable	
8. Exposure controls / personal protection			
Engineering measures to minimize worker exposure: None.			
Personal protection:			
	Respiratory protection: Hand protection:	None (except when the product burds fr. section 4 & 10 Gloves in case of frequent contact with warm material.	<i>ı</i>).
	Eye protection:	Safety goggles during machining	
Industrial hygiene: Follow good standard industrial practice. No special precautions.			
9. Physical and chemical properties			
Appearance		Form: Stock shapes (plate and rod)	ACCORDING TO
		Colour: Watural (white) / black	
Odour:		No special odour	
Change in physical state:		Boiling point/boiling range: Not applicable Melting point/melting range: 175°C	
Flash point:		Not applicable	
Vapour pressure:		Not applicable	
Self ignition temperature:		375°C	ASTM D 1929
pH:		Not applicable	
Density (at 23°C):		1.43 g/cm ³	ISO 1183
Solubility in water:		Negligible	
Thermal decomposition:		> 230°C	



10. Stability and reactivity



www.quadrantplastics.com

or products by the buyer