






6. Accidental release measures **Personal precautions:** Not applicable **Environmental precautions:** See section 12 & 13 Methods for cleaning up: See section 13 R 7. Handling and storage Handling: **Technical measures:** Not applicable **Precautions:** Not applicable During machining of the stock shapes, evacuate swarf to prevent stipping Safe handling advice: or tripping hazard Storage: Technical measures: Avoid exposure to UV-radiation Safe storage conditions: Inert under normal storage conditions Incompatible products: Not applicable Safe packaging materials: Not applicable 8. Exposure controls / personal protection Engineering measures to minimize worker exposure: None. Personal protection: None (except when the product burds - cfr. section 4 & 10). **Respiratory protection:** Gloves in case of frequent contact with warm material. Hand protection: Safety goggles during machining. Eye protection: Industrial hygiene: Follow good standard industrial practice. No special precautions. 9. Physical and chemical properties ACCORDING TO Form: Stock shapes (plate and rod) Appearance; Colour: Watural (clear, translucent) Odour: No special odour Change in physical state: Boiling point/boiling range: Not applicable Glass transition temperature: 150°C Flash point: Not applicable Vapour pressure: Not applicable Self ignition temperature: 560°C ASTM D 1929 pH: Not applicable Density (at 23°C): 1.20 g/cm³ ISO 1183 Solubility in water: Negligible Thermal decomposition: > 360°C

S





10. Stability and reactivity



www.quadrantplastics.com